

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402148470

Date Received:

08/29/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Labowskie, Steve</u>		<u>steve.labowskie@state.co.us</u>
<u>Burger, Craig</u>		<u>craig.burger@state.co.us</u>
<u>Roland, Kandis</u>		<u>kroland@hilcorp.com</u>
<u>Shorty, Priscilla</u>		<u>pshorty@hilcorp.com</u>
<u>Ray, Mandy</u>	<u>(505) 599-4083</u>	<u>mray@hilcorp.com</u>
<u>Duran, Alicia</u>		<u>alicia.duran@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693900668

Inspection Date: 08/15/2019

FIR Submit Date: 08/16/2019

FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 443138

Location Name: Anderson Number: 2-5H & 3-5H County: LA PLATA

Qtrqtr: SESE Sec: 5 Twp: 32N Range: 6W Meridian: N

Latitude: 37.039400 Longitude: -107.515400

FACILITY - API Number: 05-067- -00 Facility ID: 443139

Facility Name: ANDERSON Number: 3-5H

Qtrqtr: SESE Sec: 5 Twp: 32N Range: 6W Meridian: N

Latitude: 37.039400 Longitude: -107.515400

CORRECTIVE ACTIONS:

1 CA# 129327

Corrective Action:

Date: 08/26/2019

Update the Form 7 with current well information in accordance with Rule 206. Contact COGCC engineer Alicia Duran, at (303) 894-2100 x 5690, to provide detail about what conductor and/or casings are set and why.

Response: CA COMPLETED

Date of Completion: 08/19/2019

Operator Comment: Prelim form 5 filed to show setting of surface casing.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 129328

Corrective Action: Remove and properly dispose of waste and debris. Manage non-noxious weeds (ie mow) such as kochia to prevent debris.

Date: 08/30/2019

Response: CA COMPLETED

Date of Completion: 08/30/2019

Operator Comment: Wellhead guards will be installed and trash picked up by 8-30-19

COGCC Decision: _____

COGCC Representative: _____

3 CA# 129329

Corrective Action: Control weeds. Corrective action to control weeds is back-dated to document ongoing weed control non-compliance. Interim reclamation needs to be conducted during the fall 2019 seeding window, and no later than November 1, 2019.

Date: 05/20/2017

Response: CA COMPLETED

Date of Completion: 08/30/2019

Operator Comment: Four Corners weed control scheduled to spray the weeds along the access road, pipeline ROW and location by 8-30-19

COGCC Decision: _____

COGCC Representative: _____

4 CA# 129330

Corrective Action: Erosion and bare soils need to be stabilized immediately. Reclaimed soils will need erosion controls during site stabilization. All stormwater and erosion controls need to be selected, installed, and maintained in accordance with good engineering practices such as those described by CDOT in their erosion control manuals. Corrective action is back-dated to document time out of compliance.

Date: 11/30/2016

Response: CA COMPLETED

Date of Completion: 08/29/2019

Operator Comment: Hilcorp received a FIR noting that the well is still being reported as DG status. After research, it was found that XTO did not file a Form 5 to show that surface casing was set and then operations were suspended. Hilcorp has since refiled the APD's to change the plans, the APD's are currently pending approval. APD document numbers are: 401915712, 401915908, 401915965. Since this location is still technically an active site, reclamation can not take place yet.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Hilcorp received a FIR noting that the well is still being reported as DG status. After research, it was found that XTO did not file a Form 5 to show that surface casing was set and then operations were suspended. Hilcorp has since refiled the APD's to change the plans, the APD's are currently pending approval. APD document numbers are: 401915712, 401915908, 401915965

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amanda Walker

Signed: _____

Title: Operation/Regulatory Tech

Date: 8/29/2019 2:37:21 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402148485	Prelim Form 5
-----------	---------------

Total Attach: 1 Files