

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/30/2019

Submitted Date:

09/04/2019

Document Number:

688000335

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: YOUNG, ROB On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10112
 Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
 Address: 5057 KELLER SPRINGS RD STE 650
 City: ADDISON State: TX Zip: 75001

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	

General Comment:

Environmental inspection related to nearby Complaint #200448016. There is a partially buried oil skim pit and a tinhorn (culvert) associated with Pit Facility ID 112069. Active Rem #9288 should be closed with a new eForm 27 describing the tinhorn closure plan. It is likely that the partially buried oil skim tank would need to be removed in order to facilitate closure of the tinhorn and it can be included in the same Form 27. Contact NE EPS Rob Young with any questions.

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 112069 Lat: 40.651460 Long: -103.869821

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: A culvert (tinhorn) and partially buried oil skim tank are associated with Pit Facility ID 112069 and require closure under an approved eForm 27.

Corrective Action

Submit an eForm 27 describing closure of the tinhorn and potentially the oil skim tank. Submit an eForm 27 requesting closure of Rem #9288 referencing the new remediation project number.

Date: 09/20/2019

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688000337	Location photographs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4928609