

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402171526

Date Received:
09/10/2019

FIR RESOLUTION FORM

Overall Status: FRQ

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

0 CA Completed
1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Max Knop</u>	<u>303-825-4822</u>	<u>mknop@kpk.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 688500154
Inspection Date: 06/21/2019 FIR Submit Date: 09/06/2019 FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC Company Number: 46290
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 446484

Location Name: GRANT Number: _____ County: _____
Qtrqtr: NWNE Sec: 26 Twp: 2N Range: 68W Meridian: 6
Latitude: 40.116700 Longitude: -104.967740

FACILITY - API Number: 05-123-00 Facility ID: 446608

Facility Name: GRANT Number: _____
Qtrqtr: NWNE Sec: 26 Twp: 2N Range: 68W Meridian: 6
Latitude: 40.116700 Longitude: -104.967740

CORRECTIVE ACTIONS:

1 CA# 130205

Corrective Action: Submit Form 27 as required by Rule 905.b.
Submit Form 19-I as required by Rule 906.b.(1)A.
Notify Local Government as required by Rule 906.b.(2).
Notify Surface Owner as required by Rule 906.b.(3).

Date: 07/05/2019

Response: FACTUAL REVIEW REQUEST

Basis for Review: Requested documentation was submitted prior to the inspection

KPK was not removing a partially buried produced water vessel at the time of the follow-up inspection. The partially buried produced water vessel had become disconnected and floated up as a result of heavy rainfall. The

Operator
Comment:

crew on-site during the follow-up inspection was making repairs to be able to reconnect the partially buried produced water vessel.

Area of observed impacted soil has been reported in both Form 19 (Doc #402094442) and Form 27 (Doc #401839887, 401904728, 401974573, & 402094074). Impacted soil is being remediated under REM Project #12158.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Max Knop

Signed:

Title: Gen Mangr of Air Quality

Date: 9/10/2019 1:13:11 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

--	--

Total Attach: 0 Files