

Inspection Photos

09/09/2019

Operator: FOUNDATION ENERGY
MANAGEMENT LLC # 10112

Location ID: 327361
Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC # 10112

Location ID: 327361



Photo 1: Photo taken from the main access road, facing northwest. Photo shows stormwater runoff has caused erosion degradation and sediment transport off the road.



Photo 2: See comments under photo 1

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC # 10112

Location ID: 327361



Photo 3: See comments under photo 1.



Photo 4: Photo shows noxious weeds (Diffuse knapweed, white flowers) remains evident along access road.

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC # 10112

Location ID: 327361



Photo 5: See comments under photo 1.



Photo 6: See comments under photo 1.

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC # 10112

Location ID: 327361



Photo 7: See comments under photo 4.



Photo 8: Photo taken from the northeast end of the location, facing south. Photo shows stormwater erosion degradation and ponding on the location. BMPs to allow for sediment laden-free stormwater discharge insufficient or missing.

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC # 10112

Location ID: 327361



Photo 9: Photo taken from the northeast end of the location, facing southwest. See comments under photo 8.




Photo 10: Photo taken from the east end of the well location. Photo shows sediment deposition and noxious weeds (diffuse knapweed) on location.

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC # 10112

Location ID: 327361



Photo 11: Photo taken from the north end of the location. Photo shows stormwater erosion and noxious weeds (puncture vine)



Photo 12: Photo taken from the west end of the location. Photo shows noxious weeds (diffuse knapweed, white flowers) remains evident on location.