

Inspection Photos

09/09/2019

Operator: FOUNDATION ENERGY
MANAGEMENT LLC # 10112

Location ID: 455471
Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC # 10112

Location ID: 455471



Photo 1: Photo taken from the southwest end of the location, facing north. Photo 1-2 provide an overview of the location.



Photo 2: See comments under photo 1

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC # 10112

Location ID: 455471



Photo 3: Photo shows noxious weeds (Diffuse Knapweed) remaining on location.



Photo 4: See comments under photo 3

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC # 10112

Location ID: 455471



Photo 5: Photo taken from the east end of the tanks on the southeast end of the location. Photo shows secondary containment does not appear to be sufficient to contain the contents of the largest single tank and sufficient freeboard to contain precipitation.



Photo 6: See comments under photo 5.

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC # 10112

Location ID: 455471



Photo 7: See comments under photo 5.



Photo 8: Photo taken from the east central area of the location, facing southwest. Photo shows stormwater erosion degradation on location.

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC # 10112

Location ID: 455471



Photo 9: Photo taken from the east end of the location. Photo shows area where stormwater from the location runs off onto the adjacent lands



Photo 10: Continued from photo 9. Photo shows sediment deposition from stormwater runoff on adjacent lands.

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC # 10112

Location ID: 455471



Photo 11: Continued from photo 9. Photo shows sediment deposition from stormwater runoff on adjacent lands.



Photo 12: Photo of stormwater erosion degradation on the north end of the location.

Inspection Photos

Operator Name: FOUNDATION ENERGY MANAGEMENT LLC # 10112

Location ID: 455471



Photo 13: Photo taken from the tanks on the north end of the location. Photo shows stormwater erosion appears to be undermining the tanks.



Photo 14: Continued from photo 14.