

Inspection Photos

API: 05-071-06223

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 9/12/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06223 | Date: 9/12/2019

Inspection Photos



Photo 1. The culvert near the location has filled in with sediment. Erosion needs to be controlled from the source. Corrective action was not performed since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06223 | Date: 9/12/2019

Inspection Photos



Photo 2. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06223 | Date: 9/12/2019