

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402160465

Date Received:
08/28/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10071
Name of Operator: HIGHPOINT OPERATING CORPORATION
Address: 555 17TH ST STE 3700
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

| | | |
|--------------------|---------------------|--------------------------|
| Contact Name | Phone | Email |
| <u>Matt Barber</u> | <u>303-312-8188</u> | <u>mbarber@hpres.com</u> |

COGCC INSPECTION SUMMARY:

FIR Document Number: 697500295
Inspection Date: 07/03/2019 FIR Submit Date: 07/09/2019 FIR Status: _____

Inspected Operator Information:

Company Name: HIGHPOINT OPERATING CORPORATION Company Number: 10071
Address: 555 17TH ST STE 3700
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 416448

Location Name: Fox Creek Number: 1-35H County: _____
Qtrqr: NWN Sec: 35 Twp: 12N Range: 63W Meridian: 6
W
Latitude: 40.971094 Longitude: -104.405933

FACILITY - API Number: 05-123- -00 Facility ID: 416448

Facility Name: Fox Creek Number: 1-35H
Qtrqr: NWN Sec: 35 Twp: 12N Range: 63W Meridian: 6
W
Latitude: 40.971094 Longitude: -104.405933

CORRECTIVE ACTIIONS:

1 CA# 126846

Corrective Action: Install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices. Corrective action date is the date to location was observed out of compliance, as the location should be in compliance at all times.
Operator shall take measures to comply with Rule 1004 throughout the impacted areas off Location.

Date: 07/03/2019

Response: CA COMPLETED Date of Completion: 07/19/2019

Sediment off location was cleaned up and Filtrex was installed along the western slope on 7/19 . The berm on

Operator Comment: the west side was repaired on 7/19 as well.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Matt Barber

Signed: _____

Title: Regulatory

Date: 8/28/2019 3:30:42 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number Description

| | |
|-----------|--------------------------|
| 402160465 | FIR RESOLUTION SUBMITTED |
|-----------|--------------------------|

Total Attach: 1 Files