

**TEP ROCKY MOUNTAIN LLC
STARKEY TANK PAD GM 11-33
Location # 335144**



**TEP ROCKY MOUNTAIN LLC
STARKEY TANK PAD GM 11-33
Location # 335144**



Cut wall behind tank battery is rilling and eroding in corner.



Sediment build up in ditch.

**TEP ROCKY MOUNTAIN LLC
STARKEY TANK PAD GM 11-33
Location # 335144**



Sediment build up in ditch.



Checkdam need maintained.

**TEP ROCKY MOUNTAIN LLC
STARKEY TANK PAD GM 11-33
Location # 335144**



Culvert at entrance need cleaned out and maintained.



Culvert at entrance need cleaned out and maintained.

**TEP ROCKY MOUNTAIN LLC
STARKEY TANK PAD GM 11-33
Location # 335144**



Rills on entrance road.



Rills on entrance road.