

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402182649

Date Received:
09/19/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10261

Name of Operator: BAYSWATER EXPLORATION & PRODUCTION LLC

Address: 730 17TH ST STE 500

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Ryan Sokolowski

720-822-2276

wellinspections@bayswater.us

rsokolowski@bayswater.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 697500289

Inspection Date: 07/03/2019

FIR Submit Date: 07/08/2019

FIR Status: _____

Inspected Operator Information:

Company Name: BAYSWATER EXPLORATION & PRODUCTION LLC

Company Number: 10261

Address: 730 17TH ST STE 500

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 455456

Location Name: EAST AULT Number: 18-C PAD County: _____

Qtrqtr: NWNE Sec: 18 Twp: 7N Range: 65W Meridian: 6

Latitude: 40.581680 Longitude: -104.704933

FACILITY - API Number: 05-123-00 Facility ID: 455456

Facility Name: EAST AULT Number: 18-C PAD

Qtrqtr: NWNE Sec: 18 Twp: 7N Range: 65W Meridian: 6

Latitude: 40.581680 Longitude: -104.704933

CORRECTIVE ACTIONS:

1 CA# 126810

Corrective Action: Comply with Rule 1002.c. The corrective date is the date the location was observed out of compliance, as the location should be in compliance at all times.

Date: 07/03/2019

Response: CA COMPLETED

Date of Completion: 08/12/2019

Operator Comment: Topsoil stockpile has been repaired and recontoured to allow for land owner's pivot irrigation system to pass through stockpile without disturbance. Topsoil stockpile has also been reseeded for erosion control. Weeds on location have been sprayed and will continue to be monitored.

COGCC Decision: _____

COGCC
Representative:

2 CA# 126811

Corrective Action: Comply with Rule 1002.e.(1).

Date: 05/31/2019

Response: CA COMPLETED

Date of Completion: 08/31/2019

Operator
Comment:

Weeds on location have been sprayed and will continue to be monitored.

COGCC Decision: _____

COGCC
Representative:

3 CA# 126812

Corrective Action: Install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices. Corrective action date is the date the location was observed out of compliance, as the location should be in compliance at all times.

Date: 07/03/2019

Response: CA COMPLETED

Date of Completion: 08/12/2019

Operator
Comment:

Additional BMPs have been installed in southeast corner and along south and west side of location to account for passage of pivot irrigation system. Existing BMPs were repaired where applicable.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ryan Sokolowski

Signed: _____

Title: Environmental Coordinator

Date: 9/19/2019 3:18:57 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

--	--

Total Attach: 0 Files