

GOLDEN EAGLE MINE E-1A API# 05-071-06411 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 26, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 6899901285



Photo 1: The noxious weeds were cut, bagged and removed from the location.

GOLDEN EAGLE MINE E-1A API# 05-071-06411 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 26, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 6899901285



Photo 2: The noxious weed rosettes were treated with herbicides.

GOLDEN EAGLE MINE E-1A API# 05-071-06411 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 26, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 6899901285



GOLDEN EAGLE MINE E-1A API# 05-071-06411 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 26, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 6899901285



Photo 4: The off site pipe was most likely from the New Elk Mine activity years ago.

GOLDEN EAGLE MINE E-1A API# 05-071-06411 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 26, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 6899901285



Photo 5: The off site pipe was removed and disposed of.

GOLDEN EAGLE MINE E-1A API# 05-071-06411 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 26, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 6899901285



Photo 6: Other debris found were removed and saved.

GOLDEN EAGLE MINE E-1A API# 05-071-06411 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 26, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 6899901285



Photo 7: The off site noxious weed rosettes were treated with herbicides.