

GOLDEN EAGLE MINE E-2 API# 05-071-06436 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 26, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901287



Photo 1: The noxious weeds were cut, bagged and removed from the location.

GOLDEN EAGLE MINE E-2 API# 05-071-06436 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 26, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901287



Photo 2: The noxious weeds were cut, bagged and removed from the location.

GOLDEN EAGLE MINE E-2 API# 05-071-06436 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 26, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901287



Photo 3: The noxious weed rosettes were treated with herbicides.

GOLDEN EAGLE MINE E-2 API# 05-071-06436 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 26, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901287



Photo 4: The noxious weeds were cut, bagged and removed from the location.