



Well Name KODEMAN #1 API Number 05 - -

Operator SKAER Permit #

Location NWSE34-9N-53W County LOGAN

Field DIVIDE Inspector R. Van Sickle

AL/PA/DA Inspection Results: Well Status:

Pass(Y)	Fail(N)	Date	FN	FD	WO	PR	SI

Surf. Csg. Size_____ Setting Depth_____ Cmt. Vol._____ WOC time_____
Consistent with APD casing Program? YES_____ NO_____ Returns_____
Rig_____ BOP'S_____ Contact_____

Prod. Csg. Set? Completion Rig/Activity

Drilling Pits: Closed Open Wellhead Installed Y N

Tank ID: Yes No N/A Skim Tank/Pit: Prod. Tanks: (2) 300 BBLs

Equipment FV-HT Meter Run: Yes No

Bradenhead Press: N/A Fluid: No Yes Type Well Cat.

Date Plugged: _____ Date Permit Expired: _____

Hole Plugged: Yes _____ No _____ Pits Backfilled: Yes _____ No _____

Material Buried: Yes _____ No _____ N/A _____ Site Clean: Yes _____ No _____

Bond Release OK: Yes _____ No _____ Fed _____ Hole Marker: Yes _____ No _____

Comments: NEEDS SIGN, TKS WEEDY.

80222

Violations: Yes ☒ No ☐ Notice Sent: Yes ☒ No ☐ Date Sent: 5-53-90

STATE OF COLORADO
OIL AND GAS CONSERVATION COMMISSION

DEPARTMENT OF NATURAL RESOURCES
SUITE 380 LOGAN TOWER BUILDING
1580 LOGAN STREET
DENVER, COLORADO 80203

WILLIAM R. SMITH
Director
DENNIS R. BICKNELL
Deputy Director

(303) 894-2100

ROY ROMER
Governor

May 22, 1990

Skaer Enterprises
P.O. Box 22418
Denver, CO 80222
Attn: Larry Skaer

Dear Sir:

In April I inspected your Rodeman #1 and Halsey #2 wells in NWSE34-9N-53W and NWNW4-8N-53W respectively of Logan County. The wells do not have signs as required by Rule 604.c(4) and the Rodeman has a lot of weeds around the tanks which need to be cleaned up. You are hereby directed to install temporary signs at these locations now and permanent signs as soon as they can be secured from the manufacturer.

If you have questions or comments please contact me at the above address or phone number.

Sincerely



Robert J. Van Sickle
Field Engineer

rjv/63v