

GOLDEN EAGLE 28-16 API# 05-071-06183 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 27, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901283



Photo 1: The areas where the Diffuse Knapweed was the dominant species were mowed using a bag to catch the clippings.

GOLDEN EAGLE 28-16 API# 05-071-06183 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 27, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901283



Photo 2: In the areas where the Diffuse Knapweed was thin, the weed was pulled out of the ground by hand including the root. Some of the roots would not come out and those stems were treated.



GOLDEN EAGLE 28-16 API# 05-071-06183 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 27, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901283



Photo 3: The weed was pulled out of the ground by hand.



GOLDEN EAGLE 28-16 API# 05-071-06183 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 27, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901283



Photo 4: When the root broke, the stem was treated.



GOLDEN EAGLE 28-16 API# 05-071-06183 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 27, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901283



Photo 5: All weeds and clippings were bagged and removed from location.

GOLDEN EAGLE 28-16 API# 05-071-06183 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 27, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901283



Photo 6: Facing north at the mowed portion of the reclamation.



GOLDEN EAGLE 28-16 API# 05-071-06183 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: SEPTEMBER 27, 2019  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901283



Photo 7: From the north fill slope of the producing Golden Eagle 28-16 facing northwest across to the Golden Eagle 28-16 reclamation.