

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402029430

Date Received:

05/01/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Santistevan, Vince

719-845-2102/719-680-9705

vincesantistevan@tcenergy.us

Mack, Ronald

ronaldmack@tcenergy.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 688401839

Inspection Date: 04/12/2019

FIR Submit Date: 04/12/2019

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 1001 17TH STREET #1000

City: DENVER

State: CO

Zip: 80202

LOCATION - Location ID: 309244

Location Name: APACHE CANYON-634S67W

Number: 29SENW

County: LAS ANIMAS

Qtrqtr: SENW

Sec: 29

Twp: 34S

Range: 67W

Meridian: 6

Latitude: 37.055982

Longitude: -104.914466

FACILITY - API Number: 05-071-

-00

Facility ID: 290652

Facility Name: APACHE CANYON

Number: 29-06

Qtrqtr: SENW

Sec: 29

Twp: 34S

Range: 67W

Meridian: 6

Latitude: 37.055982

Longitude: -104.914466

CORRECTIVE ACTIONS:

1 ☒ CA# 124232

Corrective Action: Properly treat or dispose of oily waste in accordance with 907.e

Date: 05/12/2019

Response: CA COMPLETED

Date of Completion: 04/28/2019

Operator
Comment:

The stained soil around the engine skid has been removed from the location. See attached photo log for details.

COGCC Decision: Approved

COGCC Representative: Based on Photos subitted by operator all corrective action have been completed. See inspection Doc# 693501451.

2 ☒ CA# 124233

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 04/13/2019

Response: CA COMPLETED

Date of Completion: 04/12/2019

Operator Comment: The packing has been securely fastened to stop the leaking water at the well head. See the attached photo log for details.

COGCC Decision: Approved

COGCC Representative: Based on Photos subitted by operator all corrective action have been completed. See inspection Doc# 693501451.

3 ☒ CA# 124234

Corrective Action: Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A

Date: 05/12/2019

Response: CA COMPLETED

Date of Completion: 04/28/2019

Operator Comment: The stained soil around the engine skid has been cleaned up. See attached photo log for details.

COGCC Decision: Approved

COGCC Representative: Based on Photos subitted by operator all corrective action have been completed. See inspection Doc# 693501451.

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: SR. Environmental Tech.

Date: 5/1/2019 6:04:49 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402029430	FIR RESOLUTION SUBMITTED
402029440	Photo Log

Total Attach: 2 Files