

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402189450

Date Received:

09/26/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

ronaldmack@tcenergyllc.com

ediefitzgerald@tcenergyllc.com

robfoos@tcenergyllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689901281

Inspection Date: 09/19/2019

FIR Submit Date: 09/20/2019

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 308409

Location Name: GOLDEN EAGLE-633S67W Number: 28SESE County: LAS ANIMAS

Qtrqtr: SESE Sec: 28 Twp: 33S Range: 67W Meridian: 6

Latitude: 37.138560 Longitude: -104.885170

FACILITY - API Number: 05-071- -00 Facility ID: 271279

Facility Name: GOLDEN EAGLE Number: 28-16

Qtrqtr: SESE Sec: 28 Twp: 33S Range: 67W Meridian: 6

Latitude: 37.138560 Longitude: -104.885170

CORRECTIVE ACTIONS:

1 ☒ CA# 130859

Corrective Action: Investigate. Control and contain spills/releases and clean up per Rule 906.a.

Date: 09/21/2019

Response: CA COMPLETED

Date of Completion: 09/19/2019

Operator Comment: The packing has been securely fastened to stop the leaking water at the well head. the top layer of the soil was scraped up and removed. See the attached photo log for details.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 130860

Corrective Action: Comply with Rule 1003.f. Cut, bag, and dispose of noxious weeds to prevent seed dispersal. Spray any first year biennial or perennial noxious weeds.

Date: 09/27/2019

Response: CA COMPLETED

Date of Completion: 09/24/2019

Operator Comment: The noxious weeds were cut, bagged and removed from the location. The noxious weed rosettes were treated with herbicides. See the attached photo log for details.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 ☒ CA# 130861

Corrective Action: Lower fluid level so at least two feet of freeboard exists per Rule 902.b.

Date: 09/21/2019

Response: CA COMPLETED

Date of Completion: 09/20/2019

Operator Comment: The water from the production pit was pulled by a vacuum truck to maintain two foot of freeboard. See the attached photo log for details.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: SR. Environmental Tech.

Date: 9/26/2019 7:06:52 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402189450	FIR RESOLUTION SUBMITTED
402189458	Photo log

Total Attach: 2 Files