

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402192084

Date Received:

09/27/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
		ediefitzgerald@tcenergyllc.com
		ronaldmack@tcenergyllc.com
		robfoos@tcenergyllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689901283
Inspection Date: 09/19/2019 FIR Submit Date: 09/20/2019 FIR Status:

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC Company Number: 10672
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 386507

Location Name: GOLDEN EAGLE-633S67W Number: 28SESE County: LAS ANIMAS
Qtrqtr: SESE Sec: 28 Twp: 33S Range: 67W Meridian: 6
Latitude: 37.138743 Longitude: -104.884850

FACILITY - API Number: 05-071-00 Facility ID: 217406

Facility Name: GOLDEN EAGLE Number: 28-16
Qtrqtr: SESE Sec: 28 Twp: 33S Range: 67W Meridian: 6
Latitude: 37.138743 Longitude: -104.884850

CORRECTIVE ACTIONS:

1 CA# 130862

Corrective Action: Comply with Rule 1004.e. Control noxious weeds. Date: 09/27/2019

Response: CA COMPLETED Date of Completion: 09/27/2019

Operator Comment: Some of the noxious weeds were mowed using a bag on the mower to catch the clippings. Some of the weeds were pulled out of the ground by hand, including the root. Some of the weeds were the root would not come out of the ground were cut and the stem was treated. All of the weeds and clippings were bagged and removed from

the location. See attached photo log for details.

COGCC Decision: Approved pending re-inspection

COGCC Representative: It is uncertain if mowing will be an effective control method. Seed is small and mowing could break apart seed heads dispersing the seed onto the ground. Ongoing weed control should be perform starting next year early in the season.

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed. See attached photo log for details.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: SR. Environmental Tech.

Date: 9/27/2019 5:29:49 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402192084	FIR RESOLUTION SUBMITTED
402192090	Photo Log

Total Attach: 2 Files