

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/23/2019

Submitted Date:

09/24/2019

Document Number:

689901291

FIELD INSPECTION FORM

Loc ID 309087 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
6 Number of Comments
5 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 10471
 Name of Operator: ARP PRODUCTION COMPANY LLC
 Address: 425 HOUSTON STREET SUITE 300
 City: FORTH WORTH State: TX Zip: 76102

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
MADISON RANDY		rmadison@wapitienergy.com	
JOHNSTON IAN		ijohnston@wapitienergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287870	WELL	PR	01/01/2018	GW	071-09062	VPR C 142	RI

General Comment:
 This is an interim reclamation and stormwater inspection.
 This is also a follow up of the previous inspections #689900498, 689900897, 689901032.
 Operator is directed to perform corrective actions outlined on this inspection report immediately. This inspection is being entered for notification and documentation only and is not intended to provide the Operator the opportunity to resolve the alleged violations without the imposition of a penalty, pursuant to Rule 522.c.(1). Perform corrective actions immediately to avoid further enforcement and potential penalties.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	There are List B noxious weeds growing along the main road, access road, and location. Noxious weeds observed were Musk thistle, Canada thistle, and Houndstongue. Corrective action was not completed since previous inspection. Noxious weeds have now developed seed heads which must be cut, bagged, removed, and controlled. See Attached Photos		
Corrective Action:	Comply with Rule 1003.f. Control noxious weeds.	Date:	07/10/2019
Type	WEEDS		
Comment:	Due to the extent of noxious weed infestation found field wide. The operator must submit a weed control plan for ongoing weed control practice. A detailed weed control plan should include timing of control, identification of noxious weeds, method of control, product information, equipment utilized, and location of control. It is recommended to consult the local weed control agency and have a qualified weed control expert assist with developing a field wide weed control plan. A second plan was submitted on 8/20/2019 which is under review.		
Corrective Action:	Comply with Rule 1003.f.	Date:	08/01/2019

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? **Fail**

Comment There is a pile of plastic netting at the west cut slope side of the location.

Corrective Action Comply with 1003.a.
Remove debris.

Date **10/05/2019**

Unused or unneeded equipment onsite? **Pass**

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? **Pass**

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	In Process	Check Dams	Fail			

Comment: Rock check dams were installed but have filled in with sediiment and failed. Sediment should be controlled at the source. A diversion ditch at the southwest side of the location is transporting sediment off location. Sediment has filled into the diversion ditch. There is erosion occurring along the cut slope and along the access road. Wattles along the cut slope are displaced. Stormwater BMP's must be monitored and maintianed. Corrective action was not properly completed since previous inspection. Stormwater controls must be installed to good engineering practice. See attached photos

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 07/17/2019

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402188434	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4946701
689901292	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4946676