

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/02/2019

Submitted Date:

10/02/2019

Document Number:

693501493**FIELD INSPECTION FORM**

Loc ID 455317 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 370 17TH STREET SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Carlisle, J	970-534-6006	COGCCInspections@extracti onog.com	ALL INSPECTIONS
Adamczyk, Megan		megan.adamczyk@state.co.u s	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
455315	WELL	DG	06/10/2019		014-20757	Livingston S19-25-14C	DG

General Comment:

Inspected Facilities

Facility ID: 455315 Type: WELL API Number: 014-20757 Status: DG Insp. Status: DG

Complaint

Comment: Inspection in response to complaint.
 Field Inspector Assigned: Randy Silver
 Complaint Received
 Date: 10-01-2019
 Complaint Contacted:
 Date: 09-30-2019 Time: 5:00PM via phone
 Location ID #455317
 Inspection Document # 693501484
 Complaint Document #200448172
 Nature of Complaint: Dust
 Field Inspector Actions:
 On 10-01-2019, I Randy Silver area field inspector was assigned a complaint received by COGCC staff in reference to Dust/noise. The complainant stated the issues were at the Livingston drilling pad.
 On 09-30-2019, I attempted to make contact with the complainant who indicated that on 9-30-19 she drove by the Livingston pad at approx....4:30PM on Mon 9/30 and saw a white dust coming up over the sound walls and the pad was incredibly noisy.
 I performed a complete site inspection of the oil and gas location and associated wells in the area. At time of inspection, I did not observe any unusual noise or dust on location.
 At time of inspection, I spoke with Manny Parras drilling supervisor he stated at time of complaint they were drilling he did state there was steam coming from mud chillers that could have caused that effect.
 Weather conditions: Cloudy and location wet
 See inspection document #693501484 per my inspection.
 No violation of COGCC rules were observed at the time of the inspection.
 All information reviewed and site inspection information were submitted to the COGCC for further review.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
See Doc #693501484 for full inspection	silverr	10/02/2019