

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/26/2019

Submitted Date:

09/26/2019

Document Number:

679705591

**FIELD INSPECTION FORM**

Loc ID 315299 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 74740

Name of Operator: RIO MESA RESOURCES INC

Address: P.O. BOX 984

City: RANGELY State: CO Zip: 81648

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

5 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Hayes, Mike	970-620-2257	hayespetro@centurytel.net	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230584	WELL	PR	03/01/2019	GW	103-08252	GETTY-AMOCO 29 29	PR

**General Comment:**

COGCC Inspection Report Summary.

On 9-26-2019 at approximately 13:40, inspector Rick Moran, conducted a routine inspection at Rio Mesa Resources well Getty Pan American 29 in Rio Blanco county.

The following compliance issues were observed:

- 1) 10' and 5' wide location berm missing at NW corner. Photos 2 & 3. Complete by 10-26-2019.
- 2) 1' wide low spot & animal burrow in tank berm. Photos 3 & 4. Complete by 10-26-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679705591.

**Location**Overall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Deadman # & Marked	# 4		corrective date
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	<100 BBLS	STEEL AST		40.076910,-108.845300
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	90 bbl
Other (Type)	

**Berms**

Inspector Name: Moran, Rick

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate			Inadequate	
Comment:	Animal burrow on inside of west berm. One foot wide low spot on SW corner of berm.				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4).			Date:	10/26/2019

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

<b>Inspected Facilities</b>				
Facility ID: 230584	Type: WELL	API Number: 103-08252	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Pump jack idle at time of inspection.			
Corrective Action:				Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Fail					

Comment: Missing 10' and 5' wide section of location berm in NW corner. Evidence of location run off occurring through the 10' wide section.

The White River is 40' from the missing berm section.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 10/26/2019

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402191310	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4948998">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4948998</a>
679705592	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4948981">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4948981</a>