

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402195820

Date Received:  
10/04/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 8 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Susana Lara-Mesa</u>	<u>303-825-4822</u>	<u>slaramesa@kpk.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693501476  
Inspection Date: 10/01/2019 FIR Submit Date: 10/01/2019 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC Company Number: 46290  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 332884

Location Name: CLEVELAND-62N67W Number: 28SWNW County: WELD  
Qtrqr: SWN Sec: 28 Twp: 2N Range: 67W Meridian: 6  
W  
Latitude: 40.111040 Longitude: -104.902840

FACILITY - API Number: 05-123-00 Facility ID: 240492

Facility Name: CLEVELAND Number: 2  
Qtrqr: SWN Sec: 28 Twp: 2N Range: 67W Meridian: 6  
W  
Latitude: 40.111040 Longitude: -104.902840

CORRECTIVE ACTIIONS:

4 CA# 131272

Corrective Action: Submit reports as per Rule 206. Update production records Date: 09/27/2019

Response: CA COMPLETED Date of Completion: 09/27/2019

Operator Comment: Well is not TA and does not need reports updated. There are some risers near the wellhead that are not connected to the wellhead, but are not the flowlines. The inspector's notes are not accurate

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

6 CA# 131274

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 10/02/2019

Response: CA COMPLETED

Date of Completion: 10/01/2019

Operator Comment: The repair requires a workover rig, which has been scheduled. In the meantime, the well has been blown-down and SI

COGCC Decision:

COGCC  
Representative:

8 CA# 131276

Corrective Action: Gas being vented or flared during non-upset condition without prior approval from COGCC. Rule 912 b

Date: 10/02/2019

Response: CA COMPLETED

Date of Completion: 10/01/2019

Operator Comment: The packing on the wellhead was found to be leaking after the Inspector called on Tuesday, October 1 at 1:49 pm. A pumper was on location that same day and by 3:44 pm the well had been blown down since the packing needs to be replaced, which requires a workover rig. The rig has been scheduled for this well and the well has been SI in the meantime. NO venting or flaring has occurred on this location.

COGCC Decision:

COGCC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Mani Silva

Signed:

Title: Field Supervisor

Date: 10/4/2019 10:30:31 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

<b><u>Document Number</u></b>	<b><u>Description</u></b>

Total Attach: 0 Files