

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402201024

Date Received:

10/07/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 6720
Name of Operator: ROBERT L BAYLESS PRODUCER LLC
Address: 621 17TH ST STE 2300
City: DENVER State: CO Zip: 80293

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Charles, Karen		kcharles@vefinc.com
Wells, Raymond		rwells@vefinc.com
Trujillo, Helen	505-564-7801	htrujillo@rlbayless.com
Sloan, Buddy	903-581-4382	rsloan@vefinc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693900741
Inspection Date: 08/29/2019 FIR Submit Date: 09/09/2019 FIR Status:

Inspected Operator Information:

Company Name: FAULCONER INC* VERNON E Company Number: 29200
Address: P O BOX 7995
City: TYLER State: TX Zip: 75711

LOCATION - Location ID: 325387

Location Name: INDIAN SPRINGS-N33N10W Number: 3SWNE County: LA PLATA
Qtrqtr: SWNE Sec: 3 Twp: 33N Range: 10W Meridian: N
Latitude: 37.135580 Longitude: -107.918310

FACILITY - API Number: 05-067-00 Facility ID: 214685

Facility Name: INDIAN SPRINGS Number: 2
Qtrqtr: SWNE Sec: 3 Twp: 33N Range: 10W Meridian: N
Latitude: 37.135580 Longitude: -107.918310

CORRECTIVE ACTIONS:

1 CA# 130248

Corrective Action: Controls weeds. Flowering heads need to be removed, bagged, and properly disposed. Thistle rosettes need to be controlled. Subsequent treatment will likely be needed. Additional seeding/revegetation will be required if vegetation is damaged by weed treatment activities.

Date: 09/20/2019

Response: CA COMPLETED

Date of Completion: 10/04/2019

Operator Comment: WEEDS REMOVED, THEN SPRAYED FOR ANNUAL WEED SPRAYING

COGCC Decision: _____

COGCC Representative: _____

2 CA# 130249

Corrective Action: Stormwater erosion needs to be controlled within the project area. Stormwater controls need to be selected, sized, installed, and maintained using good engineering practices such as those described in CDOT manuals for erosion control. Access road needs to be repaired and stabilized.

Date: 09/27/2019

Response: CA COMPLETED _____

Date of Completion: 10/04/2019

Operator Comment: EROSION FIXED ON PAD AND ROAD

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: WELL ACQUIRED BY ROBERT L. BAYLESS, PRODUCER LLC - AWAITING COGCC CHANGE OF OP. PLEASE CONTACT BAYLESS WITH ANY QUESTIONS. PLEASE SEE ATTACHED PHOTOS.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: HELEN TRUJILLO _____

Signed: _____

Title: PROD & REG ANALYST _____

Date: 10/7/2019 8:56:31 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

402201037	PHOTOS
-----------	--------

Total Attach: 1 Files