

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402209050

Date Received:
10/14/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290 Contact Name and Telephone:
Name of Operator: KP KAUFFMAN COMPANY INC Name: _____
Address: 1675 BROADWAY, STE 2800 Phone: () _____ Fax: () _____
City: DENVER State: CO Zip: 80202 Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Susana Lara-Mesa</u>	<u>303-825-4822</u>	<u>slaramesa@kpk.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 690101381
Inspection Date: 08/22/2019 FIR Submit Date: 09/06/2019 FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC Company Number: 46290
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

LOCATION - Location ID:

Location Name: _____ Number: _____ County: _____
Qtrqtr: SESE Sec: 1 Twp: 1N Range: 68W Meridian: 6
Latitude: 40.073302 Longitude: -104.961341

FACILITY - API Number: 05-123-00 Facility ID: 467047

Facility Name: Leppla Number: _____
Qtrqtr: SESE Sec: 1 Twp: 1N Range: 68W Meridian: 6
Latitude: 40.073302 Longitude: -104.961341

CORRECTIVE ACTIONS:

1 CA# 130206

Corrective Action:

Date: 10/07/2019

Email information outlined below to COGCC Inspector and update CA section of supplemental form 19 spill report to include the following (pertaining to compliance of COGCC series 1100 flowline regulations):

- 1) Final determination of root cause of flowline (consolidation line) failure resulting in this release
- 2) Measures taken to prevent the problem from reoccurring at this location and other points along the flowline
- 3) Detailed written description of all repairs, replacements and abandonment work completed (at spill ID #467047)
- 4) Satisfactory post repair pressure tests shall be completed by the operator prior to returning the consolidation line to service; email copy of pressure testing chart to COGCC Integrity Inspector for review (Contact COGCC Inspector regarding upcoming scheduling of flowline pressure testing).
- 5) The Lat/ Longs submitted by the operator for the location of the spill is inaccurate. Provide updated location information to COGCC Environmental Staff.

Response: CA COMPLETED _____

Date of Completion: 10/07/2019

Operator
Comment:

KPK has submitted all requested documents via email on 10-07-2019.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Max Knop

Signed: _____

Title: Environmental Specialist

Date: 10/14/2019 3:01:54 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files