

LARAMIE ENERGY, LLC
CC 604-41-32 Pad (335902)
"Frac" Water Release

Date Of Occurrence: 10/09/19

Initial Volume Estimate: 5-10 bbls

Cause: Contractor Failed to follow Procedure and Drained Hoses on Ground instead of purging with Water Truck. (Still under investigation)



LARAMIE ENERGY, LLC
CC 604-41-32 Pad
“Frac” Water Release

