

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402202287

Date Received:  
10/08/2019

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

OGCC Operator Number: 10672  
Name of Operator: TIMBER CREEK OPERATING LLC  
Address: 6295 GREENWOOD PLAZA BLVD #100  
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
		<a href="mailto:robfoss@tcenergyllc.com">robfoss@tcenergyllc.com</a>
		<a href="mailto:ediefitzgerald@tcenergyllc.com">ediefitzgerald@tcenergyllc.com</a>
		<a href="mailto:ronaldmack@tcenergyllc.com">ronaldmack@tcenergyllc.com</a>

**COGCC INSPECTION SUMMARY:**

FIR Document Number: 689901231  
Inspection Date: 09/12/2019 FIR Submit Date: 09/13/2019 FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: TIMBER CREEK OPERATING LLC Company Number: 10672  
Address: 6295 GREENWOOD PLAZA BLVD #100  
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

**LOCATION** - Location ID: 308966

Location Name: APACHE CANYON-634S67W Number: 18SWNE County: LAS ANIMAS  
Qtrqtr: SWNE Sec: 18 Twp: 34S Range: 67W Meridian: 6  
Latitude: 37.087418 Longitude: -104.926258

**FACILITY** - API Number: 05-071- -00

Facility ID: 285970

Facility Name: APACHE CANYON Number: 18-07  
Qtrqtr: SWNE Sec: 18 Twp: 34S Range: 67W Meridian: 6  
Latitude: 37.087418 Longitude: -104.926258

**CORRECTIVE ACTIIONS:**

1  CA# 130556

Corrective Action: Comply with Rule 603.f.  
Remove unused equipment.

Date: 10/14/2019

Response: CA COMPLETED

Date of Completion: 10/03/2019

The sound walls were in the way of BMP implementation activities. The BMP's were installed and the sound wall were put back in place. See attached photo log for details.

Operator  
Comment:

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2  CA# 130557

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 10/14/2019

Response: CA COMPLETED

Date of Completion: 10/03/2019

Operator  
Comment:

The bar ditch was dominated to direct run off to the culvert inlets. Erosion control blankets were installed to stabilize the disturbed soil. Rock socks were installed in the bar ditch to filter sediment. See photo attachment for details.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: \_\_\_\_\_

Title: SR. Environmental Tech.

Date: 10/8/2019 7:59:04 AM

#### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402202287	FIR RESOLUTION SUBMITTED
402202291	Photo Log

Total Attach: 2 Files