

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402211131

Date Received:

10/16/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

| Contact Name | Phone | Email |
|--------------------------|-----------------------|----------------------------|
| <u>Ray, Mandy</u> | <u>(505) 599-4083</u> | <u>mray@hilcorp.com</u> |
| <u>Shorty, Priscilla</u> | | <u>pshorty@hilcorp.com</u> |

COGCC INSPECTION SUMMARY:

FIR Document Number: 693900814

Inspection Date: 09/16/2019

FIR Submit Date: 09/23/2019

FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 306777

Location Name: TIFFANY-N32N7W Number: 1NWSW County: LA PLATA

Qtrqr: NWS Sec: 1 Twp: 32N Range: 7W Meridian: N
W

Latitude: 37.043930 Longitude: -107.565490

FACILITY - API Number: 05-067-00 Facility ID: 264203

Facility Name: TIFFANY Number: 1R

Qtrqr: NWS Sec: 1 Twp: 32N Range: 7W Meridian: N
W

Latitude: 37.043930 Longitude: -107.565490

CORRECTIVE ACTIIONS:

1 CA# 130965

Corrective Action: Revegetation needs to be conducted throughout the areas not needed for production operations. Mulching is recommended for successful vegetation establishment and erosion control.

Date: 11/15/2019

Response: CA COMPLETED

Date of Completion: 10/15/2019

The weeds were removed, areas were disked and re-seeded.

Operator Comment: _____

COGCC Decision: _____

COGCC Representative: _____

2 CA# 130966

Corrective Action: Stormwater and erosion controls such as mulch and perimeter controls, need to be installed to stabilize erosion within the project area. Erosion controls should be installed in coordination with revegetation efforts.

Date: 11/15/2019

Response: CA COMPLETED

Date of Completion: 10/15/2019

Operator Comment: Berms and drainage problems were also corrected.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amanda Walker

Signed: _____

Title: Operation/Regulatory Tech

Date: 10/16/2019 9:39:43 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|------------------------|--------------------|
| 402211134 | Well Sign |
| 402211137 | Weeds removed |
| 402211139 | Disc & Reseeded |
| 402211141 | Disc & Reseeded 2 |
| 402211146 | Disc & Reseeded 3 |
| 402211158 | Drainage |
| 402211160 | Reseeded |

Total Attach: 7 Files