

BMC D Corrective Actions

Rilling occurring on the floor of the diversion ditch has been raked and seeded.



rilling and "sediment migration" along the north west corner has been raked, seeded and mulched.



Entire west side of pad has been seeded via hand broadcasting.