

**STATE OF
COLORADO**

Facility ID 468839
A27 12 inch poly line rupture
Doc# 2573009
10/24/2019

Heil - DNR, John <john.heil@state.co.us>

RE: [EXT]:A27 12 inch line

4 messages

Henry, Jen <Jennifer.Henry@encana.com>

Thu, Oct 24, 2019 at 10:15 AM

To: "Heil - DNR, John" <john.heil@state.co.us>

Cc: "Buck, Paul" <Paul.Buck@encana.com>, Alex Fischer - DNR <alex.fischer@state.co.us>

Good morning John,

I am waiting for a full summary from our field crew and will send you an update when I have a more thorough description, but repairs began on Monday and are ongoing. Because the company that installed it initially is no longer in the area we are having to use a crew that is unfamiliar with it/ the site and have had to modify some things to fit. From what I understand this is an unusual use of this type of pipe so repairing it is more complicated than it first appears.

I will update you when I have more information, but I didn't want to leave you hanging. Matt is driving back from Denver today, and with all the snow on I-70 it may be a while before we hear from him.

Let me know if I can help you with anything else in the meantime,

Jen

Jen Henry, P.G.

Environmental Specialist

t 720.876.3043**c** 720.982.8429**Encana Services Company Ltd.****370 17th St., Suite 1700****Denver, CO 80202****encana.com**

Encana Services Company Ltd. provides
operational, corporate, administrative and
advisory services to Encana Corporation
and its subsidiaries.

From: Heil - DNR, John <john.heil@state.co.us>
Sent: Thursday, October 24, 2019 9:06 AM
To: Henry, Jen <Jennifer.Henry@encana.com>
Cc: Buck, Paul <Paul.Buck@encana.com>; Alex Fischer - DNR <alex.fischer@state.co.us>
Subject: [EXT]:A27 12 inch line

EXTERNAL EMAIL. Do not click or open attachments unless you recognize the sender and know the content is safe.

Hello Jen,

Can you please provide an update on the ruptured 12-inch poly line.

Thank you,

--

John Heil
Environmental Protection Specialist



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

C 970-787-0029 | P 303.894.2100 x5692 | O 970-625-1213
[1818 Taughenbaugh Blvd., STE 103, Rifle, CO 81650](mailto:John.Heil@state.co.us)
John.Heil@state.co.us | www.colorado.gov/cogcc

Henry, Jen <Jennifer.Henry@encana.com>
To: "Heil - DNR, John" <john.heil@state.co.us>
Cc: "Buck, Paul" <Paul.Buck@encana.com>, Alex Fischer - DNR <alex.fischer@state.co.us>

Fri, Oct 25, 2019 at 8:51 AM

Hi John,

Matt got back to me after he got home yesterday evening with the following updates. For clarification, D&B is the company that can do the poly pipe fusing now that Willow Creek has left:

10/18. Met with D&B to go over project and come up with plan.

10/21 D&B had to go get a piece of poly piping to build new boots to hold thin wall pipe correctly in fusing machine. This being an abnormal pipe doesn't cross reference for ease of use.

10/21 - 10/23 build boots to fit pipe and braces to support pipe after waterfall.

10/24 - mobed equipment and began fusing. A new section of pipe was brought up to close the gap between the split sections. New section fused to south end first, took over two hours to fuse (usually takes 10 min). Original piping is deformed in oval shape and doesn't line up to get correct fuse. Diameters have to match for efficiency. Northern section is unable to make correct shape to get the diameters to line up. There is a run of about 100' with this issue. We cannot just cut and slide back, more piping is needed. D&B has more pipe, going to bring up in morning 10/25 and complete run to vault. Poly pipe put back into same location in drainage until we can fuse on new run in the morning.

Will have an update in later morning.

Once I have more information for you I will let you know. Feel free to give me a call if you need anything!

[Quoted text hidden]

Henry, Jen <Jennifer.Henry@encana.com>

Fri, Oct 25, 2019 at 9:15 AM

To: "Heil - DNR, John" <john.heil@state.co.us>

Cc: "Buck, Paul" <Paul.Buck@encana.com>, Alex Fischer - DNR <alex.fischer@state.co.us>

John – wanted to pass along a bit of good news while we are waiting for the final repair update, the quarterly samples from both the spring and the seep were non-detect for all BTEX.

Jen

[Quoted text hidden]

Heil - DNR, John <john.heil@state.co.us>

Fri, Oct 25, 2019 at 1:30 PM

To: "Henry, Jen" <Jennifer.Henry@encana.com>

Cc: "Buck, Paul" <Paul.Buck@encana.com>, Alex Fischer - DNR <alex.fischer@state.co.us>

Awesome, thanks for the update!

[Quoted text hidden]