

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401901236

Date Received:

01/10/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10412

Name of Operator: AUSCO PETROLEUM INC

Address: 113 N SANTA FE AVENUE

City: FLORENCE State: CO Zip: 81226

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Tim Hart</u>	<u>303-999-5420</u>	<u>thart@fremontpetroleum.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 691401745

Inspection Date: 01/03/2019

FIR Submit Date: 01/03/2019

FIR Status: _____

Inspected Operator Information:

Company Name: AUSCO PETROLEUM INC

Company Number: 10412

Address: 113 N SANTA FE AVENUE

City: FLORENCE State: CO Zip: 81226

LOCATION - Location ID: 429093

Location Name: Pathfinder Number: C 11-12 1 County: _____

Qtrqr: NWN Sec: 12 Twp: 20S Range: 70W Meridian: 6
W

Latitude: 38.328794 Longitude: -105.178678

FACILITY - API Number: 05-043-00 Facility ID: 429093

Facility Name: Pathfinder Number: C 11-12 1

Qtrqr: NWN Sec: 12 Twp: 20S Range: 70W Meridian: 6
W

Latitude: 38.328794 Longitude: -105.178678

CORRECTIVE ACTIIONS:

1 CA# 121484

Corrective Action: Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d.

Date: 02/03/2019

Response: CA COMPLETED

Date of Completion: 01/06/2019

Operator Comment: Stained soil was removed and replaced with clean soil below the ECD. See attached photo image. Valves, pipes and fittings were checked for wear and proper fitting and then tightened or replaced to assure good, mechanical conditions.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Operator took immediate action to inspect all valves, pipes and fittings for proper fitting, tightness, leaking, and then tightened or replaced fittings, as necessary.

Operator took immediate action to remove stained soil under ECD and replaced with clean soil.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tim Hart

Signed: _____

Title: President & CEO

Date: 1/10/2019 2:55:31 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
401901236	FIR RESOLUTION SUBMITTED
401901279	Photo image

Total Attach: 2 Files