

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401901285

Date Received:

01/10/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10412

Name of Operator: AUSCO PETROLEUM INC

Address: 113 N SANTA FE AVENUE

City: FLORENCE State: CO Zip: 81226

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Tim Hart

303-999-5420

thart@fremontpetroleum.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 691401747

Inspection Date: 01/03/2019

FIR Submit Date: 01/03/2019

FIR Status: _____

Inspected Operator Information:

Company Name: INCREMENTAL OIL & GAS (FLORENCE) LLC

Company Number: 10417

Address: 600 17TH ST SUITE 2625 SOUTH

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 425246

Location Name: Swordfish Number: 13-31 County: _____

Qtrqtr: Lot 2 Sec: 31 Twp: 19S Range: 69W Meridian: 6

Latitude: 38.349677 Longitude: -105.159650

FACILITY - API Number: 05-043- -00 Facility ID: 425246

Facility Name: Swordfish Number: 13-31

Qtrqtr: Lot 2 Sec: 31 Twp: 19S Range: 69W Meridian: 6

Latitude: 38.349677 Longitude: -105.159650

CORRECTIVE ACTIONS:

1 ☒ CA# 121485

Corrective Action: Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d.

Date: 02/03/2019

Response: CA COMPLETED

Date of Completion: 01/09/2019

Operator Comment: Removed stained soil at wellhead. Also checked valves, pipes, fittings for proper fitting, tightness and leaks; and then tightened valves and fittings to assure good mechanical conditions.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Operator took immediate action to remove stained soil at wellhead and replaced with clean soil.

Operator took immediate action to inspect valves, pipes and fittings for improper fitting and then tightened or replaced any that did not contribute to good mechanical conditions.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tim Hart

Signed: _____

Title: President & CEO

Date: 1/10/2019 3:11:06 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401901285	FIR RESOLUTION SUBMITTED
401901291	Photo Image 2 near wellhead
401901292	Photo Image 1 near wellhead

Total Attach: 3 Files