

**Response to FIR: Document 699100309**

COGCC conducted an inspection of the Spike State CC 30-24 (Location ID 309858) on October 8, 2019. During that inspection, COGCC made the following observations:

COGCC Comment: *Location is not accessible during normal business hours.*

COGCC Corrective Action: *Repair and maintain lease road to comply with rule 204.*

Noble Response: Noble determined road inaccessibility was due to erosion. Noble has repaired the road and successfully restored accessibility. Erosion was backfilled, and the road was recompact. Photos of the repaired areas are presented in the attached log. Noble looks to continually improve their location maintenance program, and we welcome further discussion regarding these repairs.

**COGCC – 10/08/19**



COGCC Photo 2. Inaccessible lease road.

**Noble Energy – 10/15/19**



Photo NBL1. Erosion back-filled and compacted roadbed.

COGCC – 10/08/19



COGCC Photo 3. Inaccessible lease road

Noble Energy – 10/15/19



Photo NBL2. Erosion back-filled and compacted roadbed.

COGCC – 10/08/19



COGCC Photo 4. Inaccessible lease road

Noble Energy – 10/15/19



Photo NBL3. Erosion back-filled and compacted roadbed.

**COGCC – 10/08/19**



COGCC Photo 7. Inaccessible lease road

**Noble Energy – 10/15/19**



Photo NBL4. Filtrexx installed outside fence. Erosion repaired, and sloped compacted and tracked.

COGCC – 10/08/19



COGCC Photo 8. Inaccessible lease road

Noble Energy – 10/15/19



Photo NBL5. Erosion back-filled and compacted roadbed.