

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402247454

Date Received:

11/23/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 4 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10112

Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Alyssa Beard

Phone

3032448114

Email

abeard@foundationenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696200739

Inspection Date: 09/09/2019

FIR Submit Date: 09/10/2019

FIR Status: _____

Inspected Operator Information:

Company Name: FOUNDATION ENERGY MANAGEMENT LLC

Company Number: 10112

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

LOCATION - Location ID: 323461

Location Name: SOONER UNIT-68N58W Number: 28NWNE County: _____

Qtrqr: NWNE Sec: 28 Twp: 8N Range: 58W Meridian: 6

Latitude: 40.638140 Longitude: -103.865680

FACILITY - API Number: 05-123- -00 Facility ID: 323461

Facility Name: SOONER UNIT-68N58W Number: 28NWNE

Qtrqr: NWNE Sec: 28 Twp: 8N Range: 58W Meridian: 6

Latitude: 40.638140 Longitude: -103.865680

CORRECTIVE ACTIONS:

3 CA# 130307

Corrective Action: Comply with 1004 rules; Conduct final reclamation activities including, but not limited to compaction alleviation (cross-ripping to a minimum of 18 inches), recontouring/regrading and establish vegetation on location/access road with a total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil. Monitor and manage this site until passing Final Reclamation

Date: 10/31/2019

Response: CA COMPLETED

Date of Completion: 11/21/2019

Location has been cross-ripped and seeded as the temperature became optimal for seeding.

Operator
Comment:

COGCC Decision:

COGCC
Representative:

4 CA# 130308

Corrective Action: Comply with 1002.f; install or repair required BMPs in accordance with good engineering practices. A corrective action date based on the date of inspection is being provided as Operator is directed to perform corrective actions immediately.

Date: 09/09/2019

Response: CA COMPLETED

Date of Completion: 11/21/2019

Operator
Comment:

Stormwater BMPs have been put in place. Please attached photo.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: We are not marking the removal of equipment (power pole) as complete, but have been working with Morgan County REA, which is our service provider in this area. The electric service has been removed from the power pole. The power pole was left in place, however, because it is part of the greater power service for Sooner Unit and could not be removed piecemeal. However, since Foundaiton is planning to plug all of the wells in Sooner Unit, we continue to work with Morgan County REA. A figure that Morgan County provided to Foundation is attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Alyssa Beard

Signed:

Title: EHS Manager

Date: 11/23/2019 9:19:00 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402247455	Reclaim photo
402247456	Seed ticket
402247457	Morgan County power pole drawing

Total Attach: 3 Files