

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/25/2019

Submitted Date:

11/25/2019

Document Number:

680305972**FIELD INSPECTION FORM**Loc ID 312314 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 31257Name of Operator: FRITZLER RESOURCES INCAddress: P O BOX 114City: FORT MORGAN State: CO Zip: 80701**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fritzler, Gene	(970) 867-9388	gfritzler@bresnan.net	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221192	WELL	PR	02/10/2006	OW	075-09318	FEHRINGER 1	PR

General Comment:[Routine Site Inspection FIR](#)[Note to Operator: Read FIR completely and perform CA's within designated dates. See attached photographs.](#)

Location			
Lease Road:			
Type	Access		
comment:	Two track cropland		
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Satisfactory		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Satisfactory		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	Inadequate containment of containers/barrels/vessels/tanks... Provide/install containment or remove from location. Remove/Remediate affected soils from leaks/spills/releases...		
Corrective Action:	Provide/Install containment for all containers/barrels/vessels/tanks... or remove all non-contained equipment/supplies per Rule 907 series.		Date: 12/16/2019
Type	OTHER		
Comment:	Leak @ PJ and prime mover (within shed) has resulted in lubricant reaching and affecting surface soils.		
Corrective Action:	Repair gear box leaks and prime mover leaks. Remove/Remediate all affected soils @ PJ and within engine shed.		Date: 12/16/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
Lube Oil	Pump Jack	<= 1 bbl	
Comment:	Lube oil from gear box has reached surface soil. Refined products from prime mover leaks has reached surface soils within engine shed.		
Corrective Action:	Remove/Remediate all affected soils. Repair gear box leak. Soils under PJ gearbox and under prime mover within shed affected and require removal and remediation.		Date: 12/16/2019
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Other	# 0		corrective date
Comment:	No change to equipment inventoried.		
Corrective Action:			Date:
Venting:			

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--

Inspected Facilities									
Facility ID:	221192	Type:	WELL	API Number:	075-09318	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	OGW								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	In Process	Other	In Process			

Comment: [Use BMP's for erosion management](#)

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
NOTE TO OPERATOR: PLEASE READ FIR COMPLETELY AND PERFORM CA'S. NOTIFY FI GROUP OF CA'S COMPLETED. SEE ATTACHED PHOTOS.	schureky	11/25/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680306039	Sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4998348
680306040	Gear Box leak to soil	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4998349
680306041	Gear Box leaks side and front	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4998350
680306042	Gear Box leak front (close-up)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4998351
680306043	Non-containment of vessel/tank/barrel.. affected soils	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4998352
680306044	Non-containment of vessel/tank/barrel.. affected soils	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4998353