

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/18/2019

Submitted Date:

11/18/2019

Document Number:

695101752**FIELD INSPECTION FORM**Loc ID 308642 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1801 BROADWAY SUITE 350City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277849	WELL	PR	04/09/2014	GW	071-08389	FIREHAWK 34-26	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

OTHER

Comment:

PHOTO 3: AREA OF IMPACTED SOIL AROUND COMPRESSOR SKID.

Corrective Action:

Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. (THIS IS SECOND WARNING OF IMPACTED SOIL AROUND COMPRESSOR SKID, ENFORCEMENT WILL BE CONSIDERED IF CORRECTIVE ACTION IS NOT ADDRESSED PRIOR TO NEXT INSPECTION).

Date: 12/03/2019Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No

NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**Facility ID: 277849 Type: WELL API Number: 071-08389 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

**COGCC Comments**

Comment

User

Date

THIS IS A FOLLOWUP INSPECTION TO INSPECTION DOC#695100622, NOT ALL CORRECTIVE ACTIONS HAVE BEEN ADDRESSED. THIS IS THE SECOND WARNING FOR IMPACTED SOIL NEAR COMPRESSOR SKID, ENFORCEMENT WILL BE CONSIDERED IF CORRECTIVE ACTION IS NOT ADDRESSED PRIOR TO NEXT INSPECTION.

beardslt

11/18/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402242801	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4991745">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4991745</a>
695101753	INSPECTION PHTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4991738">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4991738</a>