

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402249287

Date Received:

11/26/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1801 BROADWAY SUITE 350

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Tom Beardslee

tom.beardslee@state.co.us

Distribution, Evergreen

cogcc.evergreen@enrllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 695100353

Inspection Date: 03/15/2019

FIR Submit Date: 03/15/2019

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: PIONEER NATURAL RESOURCES USA INC

Company Number: 10084

Address: 5205 N O'CONNOR BLVD STE 200

City: IRVING State: TX Zip: 75039

LOCATION - Location ID: 308120

Location Name: APPALOOSA-633S67W Number: 22SENE County: LAS ANIMAS

Qtrqtr: SENE Sec: 22 Twp: 33S Range: 67W Meridian: 6

Latitude: 37.158160 Longitude: -104.869450

FACILITY - API Number: 05-071- -00 Facility ID: 262234

Facility Name: APPALOOSA Number: 42-22

Qtrqtr: SENE Sec: 22 Twp: 33S Range: 67W Meridian: 6

Latitude: 37.158160 Longitude: -104.869450

CORRECTIVE ACTIONS:

1 CA# 123255

Corrective Action: Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A.

Date: 04/15/2019

Response: CA COMPLETED

Date of Completion: 03/18/2019

Operator Comment: OIL FROM ENGINE IS RUNNING DOWN CONCRETE AND IMPACTING SOIL. ALSO EXHAUST IS IMPACTING SOIL ON EAST SIDE OF ENGINE SKID. CLEANUP COMPLETED

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**2** CA# 123256

Corrective Action: Lower fluid level so at least two feet of freeboard exists and install freeboard marker per Rule 902.b.

Date: 03/16/2019

Response: CA COMPLETED

Date of Completion: 03/19/2019

Operator Comment: PRODUCED WATER IS ABOVE THE 2' FREEBOARD. ALSO I COULD NOT FIND A FREEBOARD MARKER. I CALLED JACK WISEMAN WITH EVERGREEN TO HAVE PIT PULLED AND INSTALL FREEBOARD MARKER

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Please see attached Photos

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Cheri Morgan

Signed: \_\_\_\_\_

Title: Regulatory Specialist

Date: 11/26/2019 1:54:54 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402249304	APPALOOSA 42-22 1
402249305	APPALOOSA 42-22 2
402249306	APPALOOSA 42-22 3
402249309	APPALOOSA 42-22 4
402249310	APPALOOSA 42-22 5
402249311	APPALOOSA 42-22 6

Total Attach: 6 Files