

P&A INSP

RECEIVED

File in duplicate for Patented and Federal lands.
File in triplicate for State lands.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL ☐ GAS ☐ OTHER ☐ Plug and Abandon
WELL WELL



2. NAME OF OPERATOR

Quest Oil Company

3. ADDRESS OF OPERATOR

1580 Lincoln Street, Suite 800, Denver, CO 80203

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)

At surface NW NE NW-6-9N-52W

At proposed prod. zone

Same

837-0073

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5. LEASE DESIGNATION & SERIAL NO.

6. INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Richerson

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

W Padroni

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

6-T9N-R52W

12. COUNTY

Logan

13. STATE

Colorado

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

PULL OR ALTER CASING

<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

MULTIPLE COMPLETE

ABANDON

CHANGE PLANS:

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL,

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

<input type="checkbox"/>
<input type="checkbox"/>
<input checked="" type="checkbox"/>

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

18. Date of work 11-14 to 11-25-85

* Must be accompanied by a cement verification report.

11/14 - 25/85

Pulled and laid down rods and tubing. Ran Sd from 5111' to 5000'.
Loaded hole. Set 5 sx cmt on Sd. Pulled 86 joints. Pulled csg
to bottom of surf. @ 290'/. Pumped 20 sx cmt. Pulled remainder
of csg. Set 10 sx's cmt in top of surf. Welded on cap.

Well is plugged and abandoned.

EXHAUSTED
OIL WELL

19. I hereby certify that the foregoing is true and correct

SIGNED

John H. Utz

TITLE Agent

DATE 3/10/86

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

UTZ