

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/10/2019

Submitted Date:

12/12/2019

Document Number:

688306468

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
 320643 _____ Sherman, Susan _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10695
 Name of Operator: BEHRENS RESOURCES INC
 Address: PO BOX 188
 City: DEER TRAIL State: CO Zip: 80135

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 3 Number of Comments
 1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Behrens, Vic	(303) 810-6382	behrens@netecin.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204241	WELL	SI	09/01/2018	OW	005-06325	SCHMIDT 2	SI

General Comment:

Annual Bradenhead Test Inspection

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	Area	Volume			corrective date
Type: Pump Jack		# 1			
Comment:					
Corrective Action:				Date:	
Type: Prime Mover		# 1			
Comment:					
Corrective Action:				Date:	
Type: Bradenhead		# 1			
Comment:					
Corrective Action:				Date:	
Type: Deadman # & Marked		# 4			
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 204241 Type: WELL API Number: 005-06325 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI since Jul 2017. Needs MIT with 30 days and Form 7's updated.

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 326 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Date: 01/13/2020

BradenHead

Comment: Bradenhead 0 psi, Casing 62 psi, Tubing 0 psi. Operator to submit Form 17.

Corrective Action: _____

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688306505	Behrens Resources Schmidt 2 well head	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5011734
688306506	Behrens Resources Schmidt 2 bradenhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5011735
688306507	Behrens Resources Schmidt 2 well sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5011736