

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985



NOTICES AND REPORTS ON WELLS

for proposals to drill or to deepen or plug back to a different reservoir.
APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

ADOBE RESOURCES CORPORATION

3. ADDRESS OF OPERATOR

1225 17th Street, Suite 2000, Denver, Colorado 80202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)
See also space 17 below.)

At surface

2200' FEL and 2100' FSL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, OR, etc.)

KB 8288

5. LEASE DESIGNATION AND SERIAL NO.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Federal

9. WELL NO.

1-35

10. FIELD AND POOL, OR WILDCAT

Coalmont

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 35, T7N-R81W

12. COUNTY OR PARISH

Jackson

13. STATE

CO

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Reentry and P&A

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Cut and leveled road and location - dug sump. Drilled out surface plug in 5-1/2", ran tubing to 4,397', and circulated hole. Perforated 5-1/2" casing @ 4,195' and 3,600'. Set retainer @ 4,000'. Cemented 5-1/2" annulus through retainer with 250 sacks 50/50 Poz with good cement returns through perfs @ 3,600'. CIP 9/24/87. POOH and WOC. Attempted to tag - cement contaminated with mud inside 5-1/2". Washed out contaminated cement to 3,700'. Perforated @ 3,585' and set retainer @ 3,400'. Squeezed perfs through retainer with 125 sacks 50/50 Poz plus 3% CaCl₂ - left 40' of cement on retainer. CIP 9/26/87. Spotted cement plug 100' to surface 9/26/87. Hauled mud to disposal pit. Filled sump, recontoured location, installed dry hole marker, and reseeded location. Work complete 9/28/87.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Engineer

DATE 10/6/87

(This space for Federal or State office use)

APPROVED BY

TITLE

DIRECTOR

DATE OCT 16 1987

CONDITIONS OF APPROVAL, IF ANY:

O & G Cons. Comm.

*See Instructions on Reverse Side