

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402115220

Date Received:

07/19/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10071

Name of Operator: HIGHPOINT OPERATING CORPORATION

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Dustin Stransky

(303) 294-7805

dstransky@hpres.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696300329

Inspection Date: 07/11/2019

FIR Submit Date: 07/12/2019

FIR Status: _____

Inspected Operator Information:

Company Name: HIGHPOINT OPERATING CORPORATION

Company Number: 10071

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 418854

Location Name: Lion Creek Number: 03-14H County: WELD

Qtrqr: SESE Sec: 14 Twp: 11N Range: 64W Meridian: 6

Latitude: 40.914786 Longitude: -104.505064

FACILITY - API Number: 05-123-00 Facility ID: 418848

Facility Name: Lion Creek Number: 03-14H

Qtrqr: SESE Sec: 14 Twp: 11N Range: 64W Meridian: 6

Latitude: 40.914786 Longitude: -104.505064

CORRECTIVE ACTIONS:

1 ☒ CA# 126996

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 08/19/2019

Response: CA COMPLETED

Date of Completion: 07/17/2019

Operator Comment: North Loadline bucket lid has been installed. In addition, all valves, pipes, and fittings have been securely fastened to ensure good mechanical conditions and properly maintained per Rule 605.d.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection.

2 ☒ CA# 126997

Corrective Action: For localized spotting of oily waste - "Properly treat or dispose of oily waste in accordance with 907.e."

Date: 08/12/2019

Response: CA COMPLETED

Date of Completion: 07/17/2019

Operator Comment: Stained soil at north loadline at bucket has been properly treated and disposed of in accordance with Rule 907.e.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection.

3 ☒ CA# 126998

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 08/12/2019

Response: CA COMPLETED

Date of Completion: 07/17/2019

Operator Comment: Small leak on the north loadline bucket has been repaired. All valves, pipes, and fittings have been securely fastened to ensure good mechanical conditions and properly maintained per Rule 605.d.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection.

4 ☒ CA# 126999

Corrective Action: For localized spotting of oily waste - "Properly treat or dispose of oily waste in accordance with 907.e."

Date: 08/12/2019

Response: CA COMPLETED

Date of Completion: 07/17/2019

Operator Comment: Stained soil at wellhead has been properly treated and disposed of in accordance with Rule 907.e.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Matt Barber

Signed:

Title: Regulatory Compliance

Date: 7/19/2019 9:58:03 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402115220	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files