

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/31/2019

Submitted Date:

12/31/2019

Document Number:

697500983**FIELD INSPECTION FORM**Loc ID 467102 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10651Name of Operator: VERDAD RESOURCES LLCAddress: 5950 CEDAR SPRINGS ROADCity: DALLAS State: TX Zip: 75235**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Regulatory@verdadoil.com	ALL INSPECTIONS
Andrews, Doug		doug.andrews@state.co.us	Northeast Location Specialist

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
467102	LOCATION	AC			-	Bringelson Fed 2021 & 2029	CI

General Comment:[This is a follow up desktop inspection to Field Inspection Report Doc.# 697500870.](#)

Location Construction

Location ID: 467102 CDP: _____

Comment: This location is not in compliance with the approved Form 2A for the permitted disturbance area of 7.00 acres which is a permit violation. Operator has overbuilt the location to ~10.88 acres (55% overbuilt). Operator stated within Form 4 Doc.# 402268524 the location was overbuilt due to Weld County stormwater requirements. Operator should have disclosed this information up front during the COGCC permitting process.

Corrective Action: Submit a revised Form 2A immediately. There is no corrective action date because this will potentially be referred to Enforcement.

Date: _____**Form 2A COAs:****Comment:** _____**Corrective Action:** _____**Date:** _____**Wildlife BMPs:****Comment:** _____**Corrective Action:** _____**Date:** _____**Comment:** _____**Corrective****Action:** _____**Date:** _____**On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected FacilitiesFacility ID: 467102 Type: LOCATION API Number: - Status: AC Insp. Status: CI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402274993	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5025142