

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402020675

Date Received:

04/25/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Sabre Beebe

970-779-9398

sabre.beebe@bpx.com

SanJuanCOGCC@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680603450

Inspection Date: 12/19/2018

FIR Submit Date: 01/02/2019

FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 312068

Location Name: BONDAD 33-9-N33N9W Number: 6NESW County: LA PLATA

Qtrqtr: NESW Sec: 6 Twp: 33N Range: 9W Meridian: N

Latitude: 37.129634 Longitude: -107.870406

FACILITY - API Number: 05-067- -00 Facility ID: 267414

Facility Name: CLOVIS A Number: 2

Qtrqtr: NESW Sec: 6 Twp: 33N Range: 9W Meridian: N

Latitude: 37.129634 Longitude: -107.870406

CORRECTIVE ACTIONS:

1 ☒ CA# 121450

Corrective Action: A long term weed control plan needs to be implemented in 2019. Multiple control methods and subsequent treatments are likely needed. Recommend contacting La Plata County weed control specialist for suggestions to manage infestations. Control weeds at the appropriate time but no later than June 1, 2019.

Date: 06/01/2019

Response: CA COMPLETED

Date of Completion: 04/29/2019

Operator Comment: Herbicide treatment around equipment and Colorado State Noxious weeds on location scheduled for 4/29/2019. All BPX locations not determined to be in NO Spray area are managed through an annual weed program by a contract vendor who specializes in weed control.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2  CA# 121451

Corrective Action: Stormwater controls and slope stabilization measures need to be installed to stabilize erosion on the well pad cut and fill slopes. Revegetation will help provide long term stabilization. Temporary erosion control measures such as natural fiber erosion control blankets, need to be installed until perennial vegetation is established.

Date: 02/15/2019

Response: CA COMPLETED

Date of Completion: 04/12/2019

Operator Comment: Location was assessed for stormwater and multiple stormwater BMP's were installed as well and clean out of existing controls. Rock rundowns installed and existing BMP's cleaned out. Seeding was performed on cut slope and covered with a coconut mat to stabilize and attempt to vegetate. Diversion ditches were cleaned out and re-established. Silt deposits were removed. Berming was established at edge of fill slope. See attached photos of work completed.

COGCC Decision: **Not Approved**

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions addressed utilizing multiple methods of stormwater BMP's and contract vendor whom specializes in weed control. See attached photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Compliance Specialist

Date: 4/25/2019 5:04:17 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402020675	FIR RESOLUTION SUBMITTED
-----------	--------------------------

402020676	Photos of work completed
-----------	--------------------------

Total Attach: 2 Files