

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402292518

Date Received:

01/22/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10071

Name of Operator: HIGHPOINT OPERATING CORPORATION

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

bjames@hpres.com

mstorey@hpres.com

stephen.lunt@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 697501032

Inspection Date: 01/16/2020

FIR Submit Date: 01/21/2020

FIR Status: _____

Inspected Operator Information:

Company Name: HIGHPOINT OPERATING CORPORATION

Company Number: 10071

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 428174

Location Name: Siebring Number: 5-63-32 County: _____

Qtrqr: SENE Sec: 32 Twp: 5N Range: 63W Meridian: 6

Latitude: 40.356667 Longitude: -104.451255

FACILITY - API Number: 05-123-00 Facility ID: 428174

Facility Name: Siebring Number: 5-63-32

Qtrqr: SENE Sec: 32 Twp: 5N Range: 63W Meridian: 6

Latitude: 40.356667 Longitude: -104.451255

CORRECTIVE ACTIONS:

1 ☒ CA# 136049

Corrective Action: Corrective Action (CA) #1: Comply with Rule 1002.b.(1) to salvage and store all topsoil to facilitate subsequent reclamation.

Date: _____

CA #2: Submit the total salvaged and stored topsoil in cubic yards.

There is no corrective action date because this might be referred to Enforcement. Please submit the requested information as soon as possible.

Response: CA COMPLETED

Date of Completion: 01/22/2020

Operator Comment: CA#1: Per Rule 1001.c., HPR has secured a Waiver from Surface Owner for Rule 1002.b.(1) to limit the disturbance of their top soil during pad construction. Additionally, HPR and Surface Owner have agreed to perform all reclamation in accordance with the rules and regulations of the COGCC per the terms of the Surface Use Agreement dated 5/7/2019.

CA#2: HPR has salvaged and stored 10,586 cy of topsoil.

COGCC Decision: **Not Approved**

COGCC Representative: CA#1: A rule waiver granted by a surface owner to Operators is not sufficient to meet the Act's requirements. The Operator must apply to the Commission for a Surface Owner Variance Request on a case-by-case basis prior to the operations (i.e., topsoil salvage operations).

CA#2: COGCC staff will conduct a follow up inspection to evaluate the amount of topsoil salvaged and stored.

OPERATOR COMMENT AND SUBMITTAL

Comment: Please contact Mike Storey or Brian James if you would like a representative from HPR for the follow up inspection.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Brian James

Signed: _____

Title: Land Manager

Date: 1/22/2020 4:04:10 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402292518	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files