

GOLDEN EAGLE 30-14 API# 05-071-08650 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: JANUARY 27, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102088



PHOTO 1: THE LEAKS FROM THE LIQUID RING COMPRESSOR WERE IDENTIFIED AND REPAIRED. THE SKID OF THE LIQUID RING COMPRESSOR WAS CLEANED AND THE FLUID ACCUMULATION REMOVED. SELF INSPECTION PROCEDURE REVIEWED BY THE SENIOR PRODUCTION FOREMAN.

GOLDEN EAGLE 30-14 API# 05-071-08650 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: JANUARY 27, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102088



PHOTO 2: THE SKID OF THE LIQUID RING COMPRESSOR WAS CLEANED AND THE FLUID ACCUMULATION WAS REMOVED FROM THE RESERVOIR.

GOLDEN EAGLE 30-14 API# 05-071-08650 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: JANUARY 27, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102088



PHOTO 3: ALL VALVES AND FITTINGS WERE SECURELY FASTENED.

GOLDEN EAGLE 30-14 API# 05-071-08650 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: JANUARY 27, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102088



PHOTO 4: ALL VALVES AND FITTINGS WERE SECURELY FASTENED. THE SKID AND THE RESERVOIR OF THE LIQUID RING COMPRESSOR WAS CLEANED AND THE FLUID ACCUMULATION REMOVED.

GOLDEN EAGLE 30-14 API# 05-071-08650 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: JANUARY 27, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102088



PHOTO 5: THE IMPACTED SOIL NEXT TO THE LIQUID RING COMPRESSOR WAS REMOVED FROM THE LOCATION.

GOLDEN EAGLE 30-14 API# 05-071-08650 – TIMBER CREEK OPERATING
OGCC OPERATOR NUMBER 10672 - DATE: JANUARY 27, 2020
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695102088



PHOTO 6: THE FLUID ACCUMULATION IN THE RESERVOIR WAS REMOVED.