

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402295920

Date Received:
01/28/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10539
Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP
Address: 1125 ESCALANTE DR
City: RANGELY State: CO Zip: 81648
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

| Contact Name | Phone | Email |
|------------------------|---------------------|------------------------------------|
| <u>Utah Gas Corp</u> | <u>720-425-0303</u> | <u>inspections@utahgascorp.com</u> |
| <u>Kellerby, Shaun</u> | <u>970-712-1248</u> | <u>shaun.kellerby@state.co.us</u> |

COGCC INSPECTION SUMMARY:

FIR Document Number: 679703770
Inspection Date: 04/17/2019 FIR Submit Date: 04/18/2019 FIR Status: _____

Inspected Operator Information:

Company Name: UTAH GAS OP LTD DBA UTAH GAS CORP Company Number: 10539
Address: 1125 ESCALANTE DR
City: RANGELY State: CO Zip: 81648

LOCATION - Location ID: 315922

Location Name: DRAGON TRAIL UNIT-62S102W Number: 21NWNW County: RIO BLANCO
Qtrqtr: NWN Sec: 21 Twp: 2S Range: 102W Meridian: 6
Latitude: 39.865349 Longitude: -108.854577

FACILITY - API Number: 05-103- -00 Facility ID: 231763

Facility Name: DRAGON TRAIL UNIT Number: 1075
Qtrqtr: NWN Sec: 21 Twp: 2S Range: 102W Meridian: 6
Latitude: 39.865349 Longitude: -108.854577

CORRECTIVE ACTIONS:

1 CA# 124389

Corrective Action: Repair or install berms or other secondary containment devices per Rule 906.d.(1).

Date: 03/08/2019

Response: CA COMPLETED

Date of Completion: 05/07/2019

Secondary containment repaired

Operator
Comment:

COGCC Decision:

COGCC
Representative:

2 CA# 124390

Corrective Action: Comply with Rule 603.f .

Date: 05/20/2019

Response: CA COMPLETED

Date of Completion: 05/07/2019

Operator
Comment:

Linder debris removed

COGCC Decision:

COGCC
Representative:

3 CA# 124391

Corrective Action: Install sign to comply with Rule 210.b.

Date: 06/17/2019

Response: CA COMPLETED

Date of Completion: 05/07/2019

Operator
Comment:

911 sign installed

COGCC Decision:

COGCC
Representative:

4 CA# 124392

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 05/20/2019

Response: CA COMPLETED

Date of Completion: 05/07/2019

Operator
Comment:

Stormwater BMP completed

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective actions were completed 5/7/19 and follow up inspection was completed 5/17/19 indicating all CA's were resolved

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Robert Bleil

Signed:

Title: Regulatory Manager

Date: 1/28/2020 9:39:01 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|-------------------------------|---|
| 402295949 | Photo of liner repair |
| 402295952 | Follow up inspection #679704115 identifying CA's as completed |

Total Attach: 2 Files