

Pit Status Evaluation Form

Pit Overview:

Pit Name: ROBBINS RANCH "D" 1	Facility ID: 114645
Current Status: Unknown	Status Date: 9/23/1999
Current Operator: TXO PRODUCTION CORP / 90735	
Updated Operator:	
Form 15 Pit Permit Doc #:	Permit Date:
Related Facilities: ROBBINS RANCH #1 (API 05-009-06291, Facility ID 205876 Loc ID 379178)	

County: BACA			
Township: 32S	Range: 42W	Section: 3	QQ: SWNW
Original Latitude/ Longitude: 37.289132 / -102.147338			
Updated Latitude/ Longitude: /			
Basis for Location Change:			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts:	<input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)
Inspection Notes:	
Operator Required to Submit Form: NA Due Date:	
Form Request Sent To: Sent Date:	

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|---|-----------------|
| <input type="checkbox"/> | Form 15 Pit Permit – Doc #: | Date: |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 565575 | Date: 10/9/1985 |
| | Doc #: 557362 | Date: 3/18/1992 |
| | Doc #: 557343 | Date: 1/18/1994 |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> | COGIS Document – Doc #: | Date: |
| <input checked="" type="checkbox"/> | Pit Inventory – Doc #: 2223928 | Date: 2/9/1998 |
| <input type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: | |
| <input type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 9/23/1999

Timing of Pit Closure:

No evidence of a pit on location. Well PA 11/24/1993, passed final inspection 1/18/1994.

Pit Status Review Summary:

Based on records review there is no evidence that there was a pit on location; inspection reports document an open top fiberglass produced water tank on location. Related well was plugged 11/24/1993 and passed final inspection 1/18/1994. Pit status has been changed to closed.