

FORM
6
Rev
05/18

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
Document Number: 402292990			
Date Received: 01/23/2020			

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: <u>81295</u>	Contact Name: <u>Cindy Lewis</u>
Name of Operator: <u>RED WILLOW PRODUCTION COMPANY</u>	Phone: <u>(970) 563-5155</u>
Address: <u>P O BOX 369</u>	Fax: _____
City: <u>IGNACIO</u> State: <u>CO</u> Zip: <u>81137</u>	Email: <u>clewis@rwpc.us</u>
For "Intent" 24 hour notice required, Name: <u>Labowskie, Steve</u> Tel: <u>(970) 946-5073</u>	
COGCC contact: Email: <u>steve.labowskie@state.co.us</u>	

API Number: <u>05-067-07672-00</u>	Well Number: <u>5-6</u>
Well Name: <u>SOUTHERN UTE FC 32-11</u>	
Location: QtrQtr: <u>SESW</u> Section: <u>5</u> Township: <u>32N</u> Range: <u>11W</u> Meridian: <u>N</u>	
County: <u>LA PLATA</u> Federal, Indian or State Lease Number: <u>BIA 750-88-1001</u>	
Field Name: <u>IGNACIO BLANCO</u> Field Number: <u>38300</u>	

Notice of Intent to Abandon Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 37.042198 Longitude: -108.069543

GPS Data:
Date of Measurement: _____ PDOP Reading: _____ GPS Instrument Operator's Name: _____

Reason for Abandonment: Dry Production Sub-economic Mechanical Problems
 Other _____

Casing to be pulled: Yes No Estimated Depth: _____

Fish in Hole: Yes No If yes, explain details below

Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below

Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
FRUITLAND COAL	1752	1918			
Total: 1 zone(s)					

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
1ST	12+1/4	8+5/8	24	270	200	270	0	VISU
2ND	7+7/8	5+1/2	15.5	2,099	340	2,099	0	VISU

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 1702 with 33 sacks cmt on top. CIPB #2: Depth _____ with _____ sacks cmt on top.
 CIBP #3: Depth _____ with _____ sacks cmt on top. CIPB #4: Depth _____ with _____ sacks cmt on top.
 CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 38 sks cmt from 320 ft. to 0 ft. Plug Type: CASING Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)
 Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged:
 Set _____ sacks at surface
 Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No
 Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. _____ inch casing Cut and Cap Date: _____
 of _____
 *Wireline Contractor: _____ *Cementing Contractor: _____
 Type of Cement and Additives Used: _____
 Flowline/Pipeline has been abandoned per Rule 1105 Yes No *ATTACH JOB SUMMARY

Technical Detail/Comments:

Information submitted as a courtesy of the Southern Ute Indian Tribe.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Cindy Lewis
 Title: Sr Petroleum Engineer Date: 1/23/2020 Email: clewis@rwpc.us

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Duran, Alicia Date: 2/3/2020

CONDITIONS OF APPROVAL, IF ANY: _____ Expiration Date: 8/2/2020

COA Type	Description

Attachment Check List

Att Doc Num	Name
402292990	FORM 6 INTENT SUBMITTED
402293213	OTHER

Total Attach: 2 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Engineer	No conditions of approval - Ute minerals and Fed surface-BLM jurisdiction.	02/03/2020

Total: 1 comment(s)