

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/03/2020

Submitted Date:

02/03/2020

Document Number:

697600784

**FIELD INSPECTION FORM**

Loc ID 456966 Inspector Name: GINTAUTAS, PETER On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10580  
Name of Operator: EXPEDITION WATER SOLUTIONS COLORADO LLC  
Address: 2015 CLUBHOUSE DR SUITE 201  
City: GREELEY State: CO Zip: 80634

**Findings:**

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		jbelt@expedition-water.com	EWS 6 facility manager
		ygoddard@expedition-water.com	
		jdemuth@petrotek.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
456307	LAND APPLICATION SITE	AC	10/05/2018		-	EWS 6 land application site	EI

**General Comment:**

Environmental inspection of EWS 6 land application site (to east of active injection facilities).  
two photos attached

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Location Construction**

Location ID: 456307 CDP: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Form 2A COAs:**

**Comment:** land application site 456307 listed as active since 10/05/2018.  
site can only be active for 3 years per COGCC policy.  
  
visual observations indicate that cuttings and/or water based muds have in general been incorporated into natve soils. Some areas may need further incorporation by tilling.

Corrective Action: close land application site by submission of site investigation and remdiation plan with adequate data to suuport that soils on land application site meet thresholds in Table 910-1 of COGCC rules.

Date: 10/04/2021

**Wildlife BMPs:**

**Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Comment:** \_\_\_\_\_

**Corrective Action:** \_\_\_\_\_

Date: \_\_\_\_\_

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Inspected Facilities**Facility ID: 456307 Type: LAND API Number: - Status: AC Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697600785	northwest corner looking south	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5055416">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5055416</a>
697600786	northeast corner looking sotuhwest	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5055417">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5055417</a>