

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402099445

Date Received:

07/16/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Susana Lara-Mesa

Phone

303-825-4822

Email

slaramesa@kpk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693500491

Inspection Date: 06/24/2019

FIR Submit Date: 06/24/2019

FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC

Company Number: 46290

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 317831

Location Name: NESSU-62N66W Number: 20NWSE County: WELD

Qtrqr: NWSE Sec: 20 Twp: 2N Range: 66W Meridian: 6

Latitude: 40.122050 Longitude: -104.797570

FACILITY - API Number: 05-123-00 Facility ID: 240034

Facility Name: NESSU Number: 15

Qtrqr: NWSE Sec: 20 Twp: 2N Range: 66W Meridian: 6

Latitude: 40.122050 Longitude: -104.797570

CORRECTIVE ACTIONS:

1 ☒ CA# 126415

Corrective Action: Install sign to comply with Rule 210.e.

Date: 07/24/2019

Response: CA COMPLETED

Date of Completion: 07/16/2019

Operator Comment: Sign has been updated. Please see attached picture.

COGCC Decision: Approved pending re-inspection

Operator wired a partial sign to bottom of old sign. Original sign still reflects old operator.

COGCC
Representative:

2 ☒ CA# 126416

Corrective Action: Properly treat or dispose of oily waste in accordance with 907.e.

Date: 07/24/2019

Response: CA COMPLETED

Date of Completion: 07/16/2019

Operator
Comment: Stained soil around WH has been removed. Please see attached picture.

COGCC Decision: Approved pending re-inspection

COGCC
Representative: Stained soil appears to be removed per doc#693501177.

3 ☒ CA# 126417

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 07/24/2019

Response: CA COMPLETED

Date of Completion: 07/16/2019

Operator
Comment: Leaking has been maintained. Saddle bearing weeds were mowed around pumping unit. Please see attached picture.

COGCC Decision: Approved pending re-inspection

COGCC
Representative: Well head appears to have been addressed. At time of inspection I PU was not running so I could not observe if saddle bearing had been repaired. Land owner will submit another complaint if squeaking from saddle bearing continues.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Alan Harrison

Signed:

Title: VP of Develop.and Prod.

Date: 7/16/2019 12:59:54 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
402099445	FIR RESOLUTION SUBMITTED
402110947	CA PIC1
402110951	CA PIC2

Total Attach: 3 Files