

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402312928

Date Received:  
02/13/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Victoria Dizghinjili

303-825-4822

vdizghinjili@kpk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 697600644

Inspection Date: 12/11/2019

FIR Submit Date: 12/13/2019

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC

Company Number: 46290

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 332889

Location Name: JOHNSON, ROLLAND A-62N66W Number: 7NWSE County: WELD

Qtrqtr: NWSE Sec: 7 Twp: 2N Range: 66W Meridian: 6

Latitude: 40.150740 Longitude: -104.817700

FACILITY - API Number: 05-123-00 Facility ID: 240892

Facility Name: JOHNSON, ROLLAND A Number: 1

Qtrqtr: NWSE Sec: 7 Twp: 2N Range: 66W Meridian: 6

Latitude: 40.150740 Longitude: -104.817700

CORRECTIVE ACTIONS:

1 CA# 135320

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a.

Date: 01/13/2020

Response: CA COMPLETED

Date of Completion: 02/10/2020

Operator Comment: Stained soil around WH and under flowline on backside of crude oil tank have been removed. Possible leak has been fixed. Please see attached pictures.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

2 CA# 135321

Corrective Action: Remove or correct whichever sign is not correct

Date: 01/13/2020

Response: CA COMPLETED

Date of Completion: 02/11/2020

Operator  
Comment: Produced water sign has been updated. Please see attached picture.

COGCC Decision:

COGCC  
Representative:

3 CA# 135322

Corrective Action: comply with rule 603.f

Date: 01/13/2020

Response: CA COMPLETED

Date of Completion: 02/11/2020

Operator  
Comment: All bullplugged risers present in area near manifold have been tagged. Please see attached pictures.

COGCC Decision:

COGCC  
Representative:

4 CA# 135323

Corrective Action: repair berm and maintain

Date: 02/08/2020

Response: CA COMPLETED

Date of Completion: 02/11/2020

Operator  
Comment: Weather conditions don't allow to repair berms right now (too freezy), but KPK will complete this CA as fast as possible.

COGCC Decision:

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Victoria Dizghinjili

Signed:

Title: Engineering Tech

Date: 2/13/2020 4:24:56 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402312943	CA PIC1
-----------	---------

402312946	CA PIC2
402312948	CA PIC3
402312949	CA PIC4
402312950	CA PIC5
402312951	CA PIC6
402312952	CA PIC7

Total Attach: 7 Files