

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402072154

Date Received:

06/12/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Ray, Mandy

(505) 599-4083

mray@hilcorp.com

Shorty, Priscilla

pshorty@hilcorp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693900099

Inspection Date: 03/18/2019

FIR Submit Date: 03/25/2019

FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 312126

Location Name: TIFFANY EAST-N32N6W Number: 17NENW County: LA PLATA

Qtrqtr: NENW Sec: 17 Twp: 32N Range: 6W Meridian: N

Latitude: 37.021480 Longitude: -107.527270

FACILITY - API Number: 05-067- -00 Facility ID: 214662

Facility Name: TIFFANY EAST Number: 2-17

Qtrqtr: NENW Sec: 17 Twp: 32N Range: 6W Meridian: N

Latitude: 37.021480 Longitude: -107.527270

CORRECTIVE ACTIONS:

1 ☒ CA# 123442

Corrective Action: Contact Area Environmental Specialist Jim Hughes at (970) 903-4072 to address potential historic release by March 27, 2019.

Date: 03/27/2019

Response: CA COMPLETED

Date of Completion: 05/10/2019

Operator Comment: Remediation is required for this site. Contact by Jennifer Deal was made to Jim Hughes and a spill report has been submitted. Remediation is slated to start in June/July 2019.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 123443

Corrective Action: Remove surface owner equipment and debris.

Date: 05/15/2019

Response: CA COMPLETED

Date of Completion: 05/15/2019

Operator
Comment: This is a FEE surface, and the equipment and debris belongs to the landowner, therefore Hilcorp can't remove since it isn't their property.

COGCC Decision: **Not Approved**

COGCC
Representative:

Operator comment does not address corrective action to remove equipment and debris on the well pad.

3 ☒ CA# 123444

Corrective Action: Conduct interim reclamation. Bare patches of soil adjacent to the southwestern fill slope need to be reclaimed. Soil remediation and temporary cattle exclusion may be needed for successful vegetation establishment.

Date: 05/17/2019

Response: CA COMPLETED

Date of Completion: 05/17/2019

Operator
Comment: Interim reclamation will be conducted after the remediation is completed.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amanda Walker

Signed: _____

Title: Operation/Regulatory Tech

Date: 6/12/2019 9:51:50 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402072154	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files