

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402096402

Date Received:

07/03/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Ray, Mandy

(505) 599-4083

mray@hilcorp.com

Shorty, Priscilla

pshorty@hilcorp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693900379

Inspection Date: 06/04/2019

FIR Submit Date: 06/05/2019

FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 326556

Location Name: HUBER-N35N8W Number: 24NENE County: LA PLATA

Qtrqtr: NENE Sec: 24 Twp: 35N Range: 8W Meridian: N

Latitude: 37.291640 Longitude: -107.689930

FACILITY - API Number: 05-067- -00 Facility ID: 257076

Facility Name: HUBER Number: 3-24

Qtrqtr: NENE Sec: 24 Twp: 35N Range: 8W Meridian: N

Latitude: 37.291640 Longitude: -107.689930

CORRECTIVE ACTIONS:

1 ☒ CA# 125841

Corrective Action: Remove and properly dispose of wood and pallet debris. This is the second corrective action for debris within the interim reclamation area.

Date: 07/05/2019

Response: CA COMPLETED

Date of Completion: 07/03/2019

Operator Comment: We did not remove the wood debris and pallets located in the northern interim reclamation project area per an agreement between the land owner and the COGCC.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Review of well file indicates permission provided to Operator to allow a small portion of the interim reclamation area on document 2209470 to be used for wood cutting. Any other permissions in this regard would not be compliant with interim reclamation regulations. Therefore this corrective action is addressed.

2 ☒ CA# 125842

Corrective Action: Stormwater controls need to be installed to stabilize erosion and manage sediment within the project area.

Date: 07/05/2019

Response: CA COMPLETED

Date of Completion: 07/03/2019

Operator Comment: Storm Water management controls have been established to stabilize erosion along western edge of access road. Check dams and diversions were installed to control water run off from location.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: PRISCILLA SHORTY

Signed: _____

Title: OperationsRegulatory Tech

Date: 7/3/2019 12:46:56 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402096402	FIR RESOLUTION SUBMITTED
402096413	Corrective Action Photos

Total Attach: 2 Files